

System/File Number 1410, 7010/07

Re: Form No. A22-6704

This Newsletter No. N22-0077

Date March 20, 1963

Previous Newsletter Nos. N22-0074

**IBM 1311 DISK STORAGE DRIVE FOR
IBM 1410 AND 7010 SYSTEMS**Additions to Direct Seek and Scan Disk SectionsPage 8

Under "Direct Seek," add a zero as the second character to all discussion of the direct seek address. The zero follows the alternate code character (*) or alternate digit). For example, in Figure 7, the additional zero goes between the * and the n. Note that both direct seek addresses and disk control fields are now ten characters long.

Page 12

Add to bottom of left column:

An attempt to execute a scan instruction in overlap mode causes an instruction check. Scan operations cannot be overlapped because the 1411 Processing Unit is used for the scan operation.